

*Split*

Page 1

# Work Order ID 57205-1

March 30, 2010 8:16:22 AM



Item ID: D412-702-105B

Accept



Setup Start



Stop



Revision ID:

Item Name: Harness Assembly

Start Date: 30/03/2010 Start Qty: 2.00



Cust Item ID:

Required Date: 05/04/2010 Req'd Qty: 2.00



Customer:

Reference:

Approvals: Process Plan: *H*

Date: *10-3-20* Tooling:

Date:

QC:

Date: SPC (Y/N):

Date:

Run Start



Stop



Sequence ID/ Work Center ID	Operation Description
--------------------------------	--------------------------

Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
----------------------	----------------	--------------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
----------	--------------

100	Pick Kit
-----	----------



0.00
------

Packaging

Memo

0.00
------

Packaging

110



0.00
------

Small Fab

Memo

0.00
------

Small Fab

Assemble as per ICA D412-702 P79

120



0.00
------

*S100413*

0.00
------

QC

Quality Control

QC5- Inspect part completeness to step on W/O

Memo

*(H)*

*10/3/20 ②*

*10/04/13 ②*



**Work Order ID 57205**

Page 2

March 30, 2010 8:16:22 AM

Item ID: D412-702-105B

Accept



Setup Start



Revision ID:

Stop



Item Name: Harness Assembly

Start Date: 30/03/2010 Start Qty: 2.00



Cust Item ID:

Required Date: 05/04/2010 Req'd Qty: 2.00



Customer:

Reference:

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop

Sequence ID/  
Work Center IDOperation  
DescriptionSet Up/  
Run HoursDraw  
NumberDraw  
Rev.Plan  
CodeAccept  
QtyReject  
QtyReject  
NumberInsp.  
Stamp

130



Identify as per dwg &amp; Stock Location: ST 294

0.00

10/4/13 C

Packaging

Memo

0.00

140



QC21- Final Inspection - Work Order Release

0.00

10/4/14 H

QC

Memo

0.00

Quality Control

mf

10-4-13



# Picklist Print

Page 1

March 30, 2010 8:16:27 AM

3

Work Order ID: 57205



Parent Item: D412-702-105B



Parent Item Name: Harness Assembly

Start Date: 30/03/2010

Required Date: 05/04/2010

Comments: IPP rev A 07.05.10 new issue EC

Start Qty: 2.00

Required Qty: 2.00

IPP Rev:B Removed Decal D3569 07-07-06 JLM

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch Purchased	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
AN960JD10LL			No				Each	3,816.000	8.0000			

Washer

Warehouse      Loc Qty      Loc Code

Location

Main Warehouse

ST349	3816
19085	376
19600	3440

D3573-1



Manufactured No

Each 13.0000 2.0000



Adapter

Warehouse      Loc Qty      Loc Code

Location

Main Warehouse

ST244	13
45926	3
55680	10

D3579-046



Manufactured No

Each 2.0000 2.0000



Shoulder Harness

Warehouse      Loc Qty      Loc Code

Location

Main Warehouse

ST272A	2
53747	2

B57229 (1)



# Picklist Print

March 30, 2010 8:16:27 AM

Page 2

Work Order ID: 57205

Parent Item: D412-702-105B

Parent Item Name: Harness Assembly

Comments: IPP rev A 07.05.10 new issue EC  
IPP Rev:B Removed Decal D3569 07-07-06 JLM



Start Date: 30/03/2010

Required Date: 05/04/2010

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch Purchased	Bin Item No	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
K62							Each	59.0000	2.0000			C



CLIP

MS21042L3



Nut

	<u>Warehouse</u> <u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
	Main Warehouse		
	ST243A	59	
	110957	9	
	113878	50	
		Each	2,045.000 8.0000

	<u>Warehouse</u> <u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
	Main Warehouse		
	ST243A	59	
	110957	9	
	113878	50	
		Each	2,045.000 8.0000

1110957

C

	<u>Warehouse</u> <u>Location</u>	<u>Loc Qty</u>	<u>Loc Code</u>
	Main Warehouse		
	ST300	2045	
	110844	35	
	111274	27	
	111668	58	
	112314	285	
	113523	17	
	113537	623	
	113644	1000	


1113537

March 30, 2010 8:16:27 AM


Shop Packet Print

Page 2





DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-117A AND  
D412-702-101B/-103B/-105B/-107B/-109B/-115B/-117B HARNESS ASSEMBLIES  
(BELTS, K6.2 CLIP AND D3569-1/-2/-3 DECAL NOT SHOWN)



DETAIL 'L' D412-702-111A/-111B/-113A/-113B HARNESS ASSEMBLIES  
(BELTS AND D3569-1/-2/-3 DECALS NOT SHOWN)

• COPYRIGHT © 2004 BY DART AEROSPACE LTD. •  
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR  
COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

**25-00-00**

